Asbestos Containing Building Materials Inspection Report

Project:

Various Buildings
Located at Camp Santiago,
Salinas, Puerto Rico

Client:
PRNG

ZEM-25449
November 2025

Prepared By:

Zimmetry Environmental Management, Corp.
www.zimmetry.com
info@zimmetry.com

Table Of Content

Section 1: Executive Summary 1

1.1 Introduction 1

1.2 Summary of Property Evaluation 1

Section 2: Asbestos Containing Building Materials Inspection Report 2

2.1 Overview of the Evaluation 2

2.2 Sampling Procedure and Results Presentation 2

2.3 Findings and Recommendations 3

2.3.1 Introduction 3

2.3.2 Homogeneous Areas with Special Considerations 3

2.3.3 Suspect Materials Presumed to be Asbestos-Containing Materials Without Laboratory Analysis 3

2.3.4 Inaccessible Areas 3

2.4 Conditions and Limitations—Disclaimer 4

2.5 Environmental Assessment Report Certification 4

Section 3: Appendices 5

List of Appendices

Appendix A: Certifications, Licenses, and Accreditations

Appendix B: Certification of No Presence of Asbestos (Form PGC-009)

Appendix C: Laboratory Results & Chain of Custody

Section 1: Executive Summary

1.1 Introduction

An Asbestos Containing Building Materials (ACBM) inspection was conducted on October 14, 2025, at Various Buildings located at Camp Santiago, in the municipality of Salinas, Puerto Rico. The asbestos-containing building materials sampling was performed to identify materials that contain asbestos fibers above allowable levels and to assist with compliance with local, state, and federal regulations.

1.2 Summary of Property Evaluation

The inspection consisted of the evaluation of the interior and exterior areas of the buildings mentioned below. **The analytical results reflect that no asbestos fibers exceeded the regulatory limits** on the analyzed samples from the inspected areas.

Table 1: Asbestos Sampling Results

Sites Inspected	Sample Results
Bldg. #199 & Gazebo	NEGATIVE
Bldg. #194 (Museum's Parking Area)	NO SAMPLES COLLECTED
Bldg. #195 (Gazebo Bathrooms)	NO SAMPLES COLLECTED
Bldg. #197 (Pool Area)	NO SAMPLES COLLECTED
Street #17	NO SAMPLES COLLECTED
Range #18 (Range Support Facility, Bathrooms & Range Operations Bldg.)	NO SAMPLES COLLECTED

Section 2: Asbestos Containing Building Materials Inspection Report

2.1 Overview of the Evaluation

This ACBM inspection is an evaluation to identify the location of material containing asbestos that exists within. Our scope of work services for these buildings consisted of the following tasks.

- A walk-through and observation of the site was performed.
- Bulk sampling of Suspected ACBM within the structure.
- Polarized Light Microscopy (PLM) Analysis of bulk samples.
- Final Inspection Report.

Throughout the inspection, the following suspected ACBM were observed and sampled:

- Ceiling Insulation Panel
- Flashing
- Roofing Material

The sampling was conducted by the Department of Natural and Environmental Resources (DRNA) of Puerto Rico and the United States Environmental Protection Agency (USEPA) accredited Inspectors qualified by experience, education, and training in recognition of potential ACBM and approved bulk sampling techniques. Direct access may have been restricted in certain areas due to physical hazards. In these cases, if any, assumptions were made based on findings from other locations whenever possible. Any such assumptions are duly noted in this report.

The inspection followed the Environmental Protection Agency recommended procedures EPA-450/2-78-014 (Parts I and II), EPA 560/5-85-024, and 40 CFR 763. These procedures call for the visual inspection of the building for suspect friable material and the collection and analysis of representative samples of suspect material.

2.2 Sampling Procedure and Results Presentation

The bulk sampling procedures utilized for the collection of the ACBM required the establishment of homogeneous sampling areas. A homogeneous sampling area is defined as an area of friable or non-friable material of a similar type that appears to be applied or constructed during the same time.

Samples collected from these predetermined homogeneous sampling areas were labeled and transported for analysis. Sample locations were identified by their current use or functional space name. Each type of asbestos displays a unique property when subject to PLM. Properties are unique to crystalline asbestos form and, therefore, can be used to identify the type of asbestos mineral as chrysotile, amosite, crocidolite, anthophyllite, tremolite, and actinolite.

The percentage of each asbestos mineral type is determined by visual estimation, which is done by mixing the sample thoroughly to provide a more accurate percentage. Any material containing over one percentage (>1%) by weight of any asbestos mineral form is considered by the USEPA to be asbestos-containing material. If disturbed, it must be handled according to specific State and Federal Regulations.

Eight (8) samples of suspected material were collected. It is our opinion that an acceptable minimum number of critical areas were sampled in keeping with the homogeneous nature of much of the material that was observed. Non-destructive sampling techniques were used. If they exist, walls, ceilings, columns, and other inaccessible areas were not broken into. It should be noted that these inaccessible areas may contain ACBM, which was not observed during the inspection. Any future construction or renovation should anticipate the presence of these materials.

The samples were received and analyzed by Eurofins Atlanta in Atlanta, GA (Certified Proficient by the National Institute of Standards and Technology (NIST) NVLAP program for bulk sample asbestos analysis; Laboratory Id 102082-0). The analysis method was polarized light microscopy with dispersion staining, as recommended by the US EPA. This survey focused on the building materials, which are present throughout the interior and exterior of the building structure.

2.3 Findings and Recommendations

2.3.1 Introduction

During the inspection, the results showed **no** asbestos fibers on the analyzed samples from the evaluated area.

2.3.2 Homogeneous Areas with Special Considerations

NONE

2.3.3 Suspect Materials Presumed to be Asbestos-Containing Materials Without Laboratory Analysis

NONE

2.3.4 Inaccessible Areas

NONE

2.4 Conditions and Limitations—Disclaimer

Zimmetry Environmental Management Corp. has performed this asbestos-containing building materials inspection thoroughly and professionally, consistent with commonly accepted industry standards. The Preparer cannot guarantee and does not warrant that this evaluation has identified all adverse environmental factors and/or conditions affecting these buildings on the evaluation date.

The results reported, and conclusions reached by the Preparer are solely for the benefit of the Owner and occupants. The results and opinions in this report, based solely on the conditions found at the buildings on the date of the evaluation, are valid only on that date. The Preparer assumes no obligation to advise the client of any changes in any actual or potential asbestos hazards at these buildings beyond the date of the evaluation.

2.5 Environmental Assessment Report Certification

Zimmetry Environmental Management Corp. has performed this asbestos-containing building materials inspection thoroughly and professionally, consistent with commonly accepted industry standards. The inspection was conducted on October 14, 2025, by Andrés A. Pagán, ASB-1025-0464-SI, qualified by experience, education, and training in recognizing asbestos-containing materials and approved sampling techniques.



Andrés A. Pagán Casillas
Environmental Asbestos Inspector

Section 3: Appendices

Appendix A: Certifications, Licenses, and Accreditations

Appendix B: Certification of No Presence of Asbestos (Form PGC-009)

Appendix C: Laboratory Results & Chain of Custody

APPENDIX A

Certifications, Licenses and Accreditations

ZIMMETRY
ENVIRONMENTAL
& INDUSTRIAL HYGIENE

United States Department of Commerce
National Institute of Standards and Technology

NVLAP®

ilac-MRA

Certificate of Accreditation to ISO/IEC 17025:2017

NVLAP LAB CODE: 102082-0

Eurofins Built Environment Testing Atlanta
Atlanta, GA

is accredited by the National Voluntary Laboratory Accreditation Program for specific services, listed on the Scope of Accreditation, for:

Asbestos Fiber Analysis

This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2017. This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality management system (refer to joint ISO-ILAC-IAF Communique on ISO/IEC 17025).

2025-10-01 through 2026-09-30
Effective Dates

DEPARTMENT OF COMMERCE * UNITED STATES OF AMERICA *

For the National Voluntary Laboratory Accreditation Program



ASB-1025-0464-SI
Número de Registro

17-sept-2026
Fecha de vencimiento

TARJETA DE REGISTRO
PARA LA REMOCION DE ASBESTO

Esta tarjeta autoriza a:

Andrés A. Pagán Casillas

Inspector

A trabajar en la remoción de asbesto en Puerto Rico. Esta persona **NO** es un empleado del DRNA.

Firma Autorizada - Departamento Recursos Naturales y Ambientales

APPENDIX B

Certification of No Presence of Asbestos (Form PGC-009)

GOBIERNO DE PUERTO RICO
OFICINA DEL GOBERNADOR
JUNTA DE CALIDAD AMBIENTAL

Área de Calidad de Agua

Forma PGC-009

CERTIFICACION DE NO PRESENCIA DE ASBESTO EN ESTRUCTURAS A DEMOLERSE

(Deberá completarse en letra de molde o impresa)

PGC-_____
PARA USO OFICIAL

Yo, Andrés A. Pagán (Nombre), mayor de edad, soltero (Estado Civil), y vecino de Bayamón (Municipio)

Dirección Postal PO Box 3545 Bayamón (Pueblo) 00958 (Zip Code)

Teléfonos: Residencial (787) 550 - 2061 Oficina (787) 995 - 0005 Ext._____

Fax (787) 995 - 0005

Certifico que:

1. La estructura localizada en Various Buildings (Bldgs. #194 (Museum Parking Area), #195 (Gazebo Bathrooms), #197 (Pool Area), #199 & Gazebo, Street #17 & Range #18 (Range Support Facility, Bathrooms & Range Operations Bldg.) located at Camp Santiago, Salinas PR, la cual será objeto de una demolición se encuentra libre de asbesto.
2. La información antes indicada es cierta y correcta.
3. Afirmo y reconozco las consecuencias de incluir y someter información falsa en este documento.
4. Para que así conste, firmo la presente certificación en Bayamón (Municipio) de Puerto Rico, hoy día 27 de octubre de 2025

_____
Firma y Sello del Profesional o
Firma del Inspector de Asbesto registrado por la JCA (Original)

Nota: Ingenieros o Arquitectos deberán someter evidencia de que se encuentra al día en el pago de sus cuotas de colegiación e Inspectores de Asbesto deberán someter evidencia de la tarjeta de registro provista por la JCA.

Dirección Física: Ave. Ponce de León 1308, Carr. Estatal 8838, Sector el Cinco, Río Piedras, PR 00926
Dirección Postal: Apartado 11488, Santurce, PR 00910-1488
Tel. (787) 767-8181 • Fax (787) 767-1962

PUERTO RICO VERDE

CERTIFICATION



TARJETA DE REGISTRO
PARA LA REMOCION DE ASBESTO

Esta tarjeta autoriza a:

Andrés A. Pagán Casillas

Inspector

A trabajar en la remoción de asbesto en Puerto Rico. Esta persona **NO** es un empleado del DRNA.

ASB-1025-0464-SI

Número de Registro

17-sept-2026

Fecha de vencimiento

Firma Autorizada - Departamento Recursos Naturales y Ambientales

APPENDIX C

Laboratory Results & Chain of Custody

ZIMMETRY
ENVIRONMENTAL
& INDUSTRIAL HYGIENE

eurofins | Built Environment Testing

October 23, 2025

Zimmetry Results
Zimmetry Environmental Mgmt Corp.
P.O. Box 3545
Bayamon, PR 958

CLIENT PROJECT: Camp Santiago Gym Bldg. 199
LAB CODE: 698150-1

Dear Zimmetry,

Enclosed are asbestos analysis results for PLM Bulk samples received at our laboratory on October 16, 2025. The samples were analyzed for asbestos using polarizing light microscopy (PLM) per the EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials and EPA 40 CFR Appendix E to Subpart E of Part 763: Interim Method of the Determination of Asbestos in Bulk Insulation Samples.

Sample results containing >1% asbestos are considered asbestos-containing materials (ACMs) per EPA regulatory requirements. The detection limit for the EPA 600 Method is <1% by calibrated visual estimate.

Thank you for your business and we look forward to continuing good relations.

Kind Regards,

Dana Till,
QA Manager

NVLAP 102082-0

eurofins | Built Environment Testing

ASBESTOS ANALYTICAL REPORT
By: Polarized Light Microscopy

Prepared for

Zimmetry Environmental Mgmt Corp.

CLIENT PROJECT:	Camp Santiago Gym Bldg. 199
LAB CODE:	698150-1
TEST METHOD:	EPA 600 / R93 / 116 and EPA 40 CFR Appendix E to Subpart E of Part 763
REPORT DATE:	10/23/25
TOTAL SAMPLES ANALYZED:	8
# SAMPLES >1% ASBESTOS:	0
TOTAL LAYERS ANALYZED:	14

3785 Presidential Parkway Suite 130, • Atlanta, GA 30340 • (770) 368-2171

eurofins | Built Environment Testing

Asbestos Report Summary
By: Polarized Light Microscopy

Project: Camp Santiago Gym Bldg. 199 **Lab Code:** 698150-1

Method: EPA 600 / R93 / 116 and EPA 40 CFR Appendix E to Subpart E of Part 763

Client ID	Lab ID	Layer	Sample Description	Asbestos %
25449-CS-01	3806307		Black tar	None Detected
25449-CS-02	3806308	Layer A	Black tar w/ silver paint	None Detected
		Layer B	Gray cementitious material	None Detected
25449-CS-03	3806309		Black tar	None Detected
25449-CS-04	3806310	Layer A	Black tar	None Detected
		Layer B	Gray cementitious material	None Detected
25449-CS-05	3806311	Layer A	Black tar	None Detected
		Layer B	Gray cementitious material	None Detected
25449-CS-06	3806312	Layer A	Black tar w/ silver paint	None Detected
		Layer B	Gray cementitious material	None Detected
25449-CS-07	3806313	Layer A	Brown felt	None Detected
		Layer B	Yellow insulation	None Detected
25449-CS-08	3806314	Layer A	Brown felt	None Detected
		Layer B	Yellow insulation	None Detected

eurofins | Built Environment Testing

ASBESTOS BULK ANALYSIS
By: Polarized Light Microscopy

Client: Zimmetry Environmental Mgmt Corp.
P.O. Box 3545
Bayamon, PR 958

Lab Code: 698150-1
Date Received: 10/16/25
Date Analyzed: 10/21/25
Date Reported: 10/23/25

Project: Camp Santiago Gym Bldg. 199

Method: ASBESTOS BULK PLM, EPA 600 METHOD

Client ID / Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS Fibrous		Non-Fibrous		ASBESTOS %
25449-CS-01	Tar	Homogeneous	30%	Glass	60%	Tar	**None Detected**
3806307		Black			10%	Foil	
		Fibrous					
		Tightly Bound					
25449-CS-02	Tar W/ Silver Paint	Homogeneous	25%	Glass	60%	Tar	**None Detected**
Layer A		Black			5%	Paint	
3806308		Fibrous			10%	Foil	
		Bound					
Layer B	Cementitious	Homogeneous			65%	Binder	**None Detected**
3806308	Material	Gray			35%	Gravel	
		Non-Fibrous					
		Bound					
25449-CS-03	Tar	Homogeneous	30%	Glass	60%	Tar	**None Detected**
3806309		Black			10%	Foil	
		Fibrous					
		Tightly Bound					
25449-CS-04	Tar	Homogeneous	30%	Glass	60%	Tar	**None Detected**
Layer A		Black			10%	Foil	
3806310		Fibrous					
		Bound					
Layer B	Cementitious	Homogeneous			65%	Binder	**None Detected**
3806310	Material	Gray			35%	Gravel	
		Non-Fibrous					
		Bound					

ASBESTOS BULK ANALYSIS
By: Polarized Light Microscopy

Client: Zimmetry Environmental Mgmt Corp.
P.O. Box 3545
Bayamon, PR 958

Lab Code: 698150-1
Date Received: 10/16/25
Date Analyzed: 10/21/25
Date Reported: 10/23/25

Project: Camp Santiago Gym Bldg. 199

Method: ASBESTOS BULK PLM, EPA 600 METHOD

Client ID / Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS Fibrous		Non-Fibrous		ASBESTOS %
25449-CS-05	Tar	Homogeneous	30%	Glass	60%	Tar	**None Detected**
Layer A		Black			10%	Foil	
3806311		Fibrous					
		Bound					
Layer B	Cementitious	Homogeneous			65%	Binder	**None Detected**
3806311	Material	Gray			35%	Gravel	
		Non-Fibrous					
		Bound					
25449-CS-06	Tar W/ Silver Paint	Homogeneous	30%	Glass	10%	Foil	**None Detected**
Layer A		Black			5%	Paint	
3806312		Fibrous			55%	Tar	
		Bound					
Layer B	Cementitious	Homogeneous			65%	Binder	**None Detected**
3806312	Material	Gray			35%	Gravel	
		Non-Fibrous					
		Tightly Bound					
25449-CS-07	Felt	Homogeneous	50%	Glass	50%	Tar	**None Detected**
Layer A		Brown					
3806313		Fibrous					
		Bound					
Layer B	Insulation	Homogeneous			100%	Foam	**None Detected**
3806313		Yellow					
		Non-Fibrous					
		Loosely Bound					

eurofins | Built Environment Testing

ASBESTOS BULK ANALYSIS
By: Polarized Light Microscopy

Client: Zimmetry Environmental Mgmt Corp.
P.O. Box 3545
Bayamon, PR 958

Lab Code: 698150-1
Date Received: 10/16/25
Date Analyzed: 10/21/25
Date Reported: 10/23/25

Project: Camp Santiago Gym Bldg. 199

Method: ASBESTOS BULK PLM, EPA 600 METHOD

Client ID / Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS Fibrous		Non-Fibrous		ASBESTOS %
25449-CS-08	Felt	Homogeneous	50%	Glass	50%	Tar	**None Detected**
Layer A		Brown					
3806314		Fibrous					
		Bound					
Layer B	Insulation	Homogeneous			100%	Foam	**None Detected**
3806314		Yellow					
		Non-Fibrous					
		Loosely Bound					

LEGEND:

Non-Anth = Non-Asbestiform Anthophyllite
Non-Trem = Non-Asbestiform Tremolite
Calc Carb = Calcium Carbonate

METHOD: EPA 600 / R93 / 116 and EPA 40 CFR Appendix E to Subpart E of Part 763

REPORTING LIMIT: 1% by calibrated visual estimation

REGULATORY LIMIT: 1%

Due to the limitations of the EPA 600 / R93 / 116 method, nonfriable organically bound materials (NOBs) such as vinyl floor tiles can be difficult to analyze via polarized light microscopy (PLM). EPA recommends that all NOBs analyzed by PLM, and found not to contain asbestos, be further analyzed by Transmission Electron Microscopy (TEM). Please note that PLM analysis of dust and soil samples for asbestos is not covered under NVLAP accreditation. Estimated measurement of uncertainty is available on request.

Eurofins Built Environment Testing East, LLC makes no warranty representation regarding the accuracy of client submitted information in preparing and presenting analytical results. Interpretation of the analytical results is the sole responsibility of the client. This report relates only to the samples tested or analyzed and may not be reproduced, except in full, without written approval by Eurofins Built Environment Testing East, LLC. Samples were received in acceptable condition unless otherwise noted. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government.

Information provided by customer includes customer sample ID and sample description.

Elena Ivanova
Analyst

DATA QA:

Kiet Nguyen
10/23/2025

APPROVED BY:

Dana Till,
QA Manager

eurofins | Built Environment Testing

RES Job #: 698150

SUBMITTED BY		INVOICE TO		CONTACT INFORMATION		SERIES
Company:	Zimmetry Environmental Mgmt Corp.	Company:	Zimmetry Environmental Mgmt Corp.	Contact:	Zimmetry Results	-1 PLM Standard
Address:	P.O. Box 3545	Address:	P.O. Box 3545	Phone:	(787) 995-0005	
	Bayamon, PR 958		Bayamon, PR 958	Fax:		
				Cell:		
Project Number and/or P.O. #:	ZEM-25449	Project Zip Code:		Final Data Deliverable Email Address:		
Project Description/Location:	Camp Santiago Gym Bldg. 199			zimmetry.labs@gmail.com (+ 4 ADDNL. CONTACTS)		

ASBESTOS LABORATORY

PLM / PCM / TEM / NYS DTL RUSH PRIORITY STANDARD

CHEMISTRY LABORATORY

Dust RUSH PRIORITY STANDARD

Metals RUSH PRIORITY STANDARD *PRIOR NOTICE REQUIRED FOR SAME DAY TAT

Organics* SAME DAY RUSH PRIORITY STANDARD

MICROBIOLOGY LABORATORY

Viable Analysis** PRIORITY STANDARD **TAT DEPENDENT ON SPEED OF MICROBIAL GROWTH

Medical Device Analysis RUSH STANDARD

Mold Analysis RUSH PRIORITY STANDARD

****Turnaround times establish a laboratory priority, subject to laboratory volume and are not guaranteed. Additional fees apply for afterhours, weekends and holidays.****

Special Instructions:

REQUESTED ANALYSIS

VALID MATRIX CODES

Air = A	Bulk = B
Dust = D	Food = F
Paint = P	Soil = S
Surface = SU	Swab = SW
Tape = T	Wipe = W
Drinking Water = DW	
Waste Water = WW	
ASTM E1792 approved wipe media only	

Client Sample ID Number (Sample ID's must be unique)	ASBESTOS: PLM - PLM Short Report (EPA/600/R-93/116)	ASBESTOS: TEM	ASBESTOS: PCM	ASBESTOS: NYS	CHEMISTRY: DUST	CHEMISTRY: METALS	CHEMISTRY: ORGANICS	MICROBIOLOGY: VIABLES	MICROBIOLOGY: MEDICAL	MICROBIOLOGY: MOLD	ICO	Sample Volume (L) / Area	Sample Temperature (°C)	Length(or Aliquots) x Width(or Area/Aliquot)	Matrix Code	# of Containers	Date Collected mm/dd/yy	Time Collected hh:mm	Laboratory Analysis Instructions
1 25449-CS-01	X														B		10/14/25	00:00	
2 25449-CS-02	X														B		10/14/25	00:00	
3 25449-CS-03	X														B		10/14/25	00:00	
4 25449-CS-04	X														B		10/14/25	00:00	
5 25449-CS-05	X														B		10/14/25	00:00	
6 25449-CS-06	X														B		10/14/25	00:00	
7 25449-CS-07	X														B		10/14/25	00:00	
8 25449-CS-08	X														B		10/14/25	00:00	

Eurofins Built Environment Testing East, LLC establishes a unique Lab Sample ID, for each sample, by preceding each unique Client Sample ID with the laboratory RES Job Number.

Eurofins Built Environment Testing East, LLC will analyze incoming samples based on information received and will not be responsible for errors or omissions in calculations resulting from the inaccuracy of original data. By signing, client/company representative agrees that submission of the following samples for requested analysis as indicated on this Chain of Custody shall consitute an analytical services agreement with payment terms of NET30. Failure to comply with payment terms may result in a 18% APR finance charge.

Relinquished By:		Zimmetry Results	Date/Time: 10/15/2025 15:50:20	Sample Condition: Acceptable
Received By:		Kiet Nguyen	Date/Time: 10/16/2025 9:56:04	Carrier: Fed-Ex

Zimmetry Environmental Mgmt Corp.
Sample Notes

RES #: 698150

Project Number and/or P.O. #: ZEM-25449

Project Description/Location: Camp Santiago Gym Bldg. 199

Client Sample ID	Sample Note	Quantity	Sampler(s)
25449-CS-01	Flashing		Andrés Pagán
25449-CS-02	Flashing		Andrés Pagán
25449-CS-03	Roofing Material		Andrés Pagán
25449-CS-04	Roofing Material		Andrés Pagán
25449-CS-05	Roofing Material		Andrés Pagán
25449-CS-06	Roofing Material		Andrés Pagán
25449-CS-07	Ceiling Insulation Panel		Andrés Pagán
25449-CS-08	Ceiling Insulation Panel		Andrés Pagán

Zimmetry Environmental Mgmt Corp.
Sample Locations

RES #: 698150

Project Number and/or P.O. #: ZEM-25449

Project Description/Location: Camp Santiago Gym Bldg. 199

Client Sample ID	Sample Location
25449-CS-01	Roof 1, Bldg. 199
25449-CS-02	Roof 2, Bldg. 199
25449-CS-03	Roof 2, Bldg. 199
25449-CS-04	Roof 2, Bldg. 199
25449-CS-05	Roof 1, Bldg. 199
25449-CS-06	Roof 3, Bldg. 199
25449-CS-07	Area 1-1, Bldg. 199
25449-CS-08	Area 1-1, Bldg. 199