PROJECT:	Various Buildings Located at Fort Allen, Juana Díaz PR			CLIENT: PRNG			
DATE:	6/27/2025	Building 231		LBP Inspector: Alicia García			
Sample ID.	Functional Space	Location	Color	Subst.	XRF Reading mg/cm2	Pos/Neg	Comments
197	Area 1-1	Beam	Brown	Metal	0.00	Negative	
198	Area 1-1	Column	Cream	Concrete	0.00	Negative	
199	Area 1-1	Floor Tile	Brown	Ceramic	0.17	Negative	
200	Area 1-1	Riser	Yellow	Concrete	0.00	Negative	
201	Area 1-1	Step	Gray	Concrete	0.00	Negative	
202	Area 1-1	Hand Rail	Brown	Metal	0.00	Negative	
203	Area 1-1	Wall A	Cream	Concrete	0.00	Negative	
204	Area 1-1	Wall B	Cream	Concrete	0.00	Negative	
205	Area 1-1	Wall C	Cream	Concrete	0.00	Negative	
206	Area 1-1	Wall D	Cream	Concrete	0.00	Negative	
207	Area 1-1	Column	Brown	Metal	0.03	Negative	
208	Area 1-1	Gate	White	Metal	0.00	Negative	
209	Area 1-1	Riser	Cream	Concrete	0.00	Negative	
210	Area 1-2	Floor Tile	Cream	Ceramic	0.00	Negative	
211	Area 1-2	Wall Tile	Cream	Ceramic	0.00	Negative	
212	Area 1-2	Door	Brown	Metal	0.00	Negative	
213	Area 1-2	Door Frame	Brown	Metal	0.00	Negative	
214	Area 1-2	Door	Brown	Metal	0.00	Negative	
215	Area 1-2	Door Frame	Brown	Metal	0.00	Negative	
216	Area 1-2	Wall A	Cream	Concrete	0.02	Negative	
217	Area 1-2	Wall B	Cream	Concrete	0.00	Negative	
218	Area 1-2	Wall C	Cream	Concrete	0.00	Negative	
219	Area 1-2	Wall D	Cream	Concrete	0.00	Negative	
220	Area 1-2	Partition	Cream	Metal	0.00	Negative	
221	Area 1-2	Toilet	White	Ceramic	0.00	Negative	
222	Area 1-2	Toilet	White	Ceramic	0.00	Negative	
223	Area 1-2	Toilet	White	Ceramic	0.00	Negative	
224	Area 1-2	Lavatory	White	Ceramic	0.00	Negative	
225	Area 1-2	Lavatory	White	Ceramic	0.00	Negative	
226	Area 1-2	Lavatory	White	Ceramic	0.01	Negative	
227	Area 1-2	Ceiling	Cream	Concrete	0.00	Negative	
228	Area 1-3	Floor Tile	White	Ceramic	0.00	Negative	
229	Area 1-3	Wall Tile	White	Ceramic	0.00	Negative	
230	Area 1-3	Wall A	Brown	Concrete	0.00	Negative	
231	Area 1-3	Wall B	Brown	Concrete	0.00	Negative	
232	Area 1-3	Wall C	Brown	Concrete	0.00	Negative	
233	Area 1-3	Wall D	Brown	Concrete	0.00	Negative	
234	Area 1-3	Lavatory	White	Ceramic	0.00	Negative	
235	Area 1-3	Lavatory	White	Ceramic	0.00	Negative	
236	Area 1-3	Lavatory	White	Ceramic	0.00	Negative	
237	Area 1-3	Toilet	White	Ceramic	0.00	Negative	
238	Area 1-3	Toilet	White	Ceramic	0.03	Negative	
239	Area 1-3	Toilet	White	Ceramic	0.00	Negative	
240	Area 1-3	Door	Brown	Metal	0.00	Negative	
241	Area 1-3	Door Frame	Brown	Metal	0.00	Negative	
242	Area 1-3	Door	Brown	Metal	0.00	Negative	
243	Area 1-3	Door Frame	Brown	Metal	0.00	Negative	
244	Area 1-3	Door	Brown	Metal	0.02	Negative	
245	Area 1-3	Door Frame	Brown	Metal	0.00	Negative	
246	Area 1-3	Door	Brown	Metal	0.00	Negative	
247	Area 1-3	Door Frame	Brown	Metal	0.00	Negative	
248	Area 1-3	Ceiling	Cream	Concrete	0.00	Negative	
249	Exterior Side A	Wall A	Brown	Concrete	0.00	Negative	
250	Exterior Side A	Wall A	Brown	Concrete	0.00	Negative	
251	Exterior Side A	Hand Rail	Brown	Metal	0.00	Negative	
252	Exterior Side A	Electrical Panel	Brown	Metal	0.00	Negative	
253	Exterior Side A	Step	Gray	Concrete	0.00	Negative	
254	Exterior Side A	Riser	Yellow	Concrete	0.00	Negative	
255	Exterior Side A	Riser	Yellow	Concrete	0.00	Negative	
256	Exterior Side A	Fascia	Brown	Concrete	0.00	Negative	

PROJECT:	Various Buildings Located at Fort Allen, Juana Díaz PR			CLIENT: PRNG			
DATE:	6/27/2025	Building 231		LBP Inspector: Alicia García			
Sample ID.	Functional Space	Location	Color	Subst.	XRF Reading mg/cm2	Pos/Neg	Comments
257	Exterior Side A	Soffit	Brown	Concrete	0.00	Negative	
258	Exterior Side A	Grille	Brown	Metal	0.00	Negative	
259	Exterior Side D	Wall D	Brown	Concrete	0.00	Negative	
260	Exterior Side D	Wall D	Brown	Concrete	0.00	Negative	
261	Exterior Side C	Wall C	Brown	Concrete	0.00	Negative	
262	Exterior Side C	Wall C	Brown	Concrete	0.00	Negative	
263	Exterior Side C	Gate	Gray	Metal	0.00	Negative	
264	Exterior Side C	Floor	Gray	Concrete	0.02	Negative	
265	Exterior Side B	Wall B	Brown	Concrete	0.00	Negative	
266	Exterior Side B	Hand Rail	Brown	Metal	0.00	Negative	
267	Exterior Side B	Grille	Brown	Metal	0.00	Negative	
268	Calibration				1.00		
269	Calibration				1.00		
270	Calibration				1.00		