PROJECT:	Various Buildings Located at Fort Allen, Juana Díaz PR			CLIENT: PRNG			
DATE:	6/27/2025	Building 233		LBP Inspector: Alicia García			
Sample ID.	Functional Space	Location	Color	Subst.	XRF Reading mg/cm2	Pos/Neg	Comments
129	Area 1-1	Door	Varnish	Wood	0.02	Negative	
130	Area 1-1	Door Frame	Varnish	Wood	0.00	Negative	
131	Area 1-1	Floor Tile	Gray	Ceramic	0.00	Negative	
132	Area 1-1	Baseboard	Gray	Ceramic	0.00	Negative	
133	Area 1-1	Wall A	Cream	Concrete	0.00	Negative	
134	Area 1-1	Wall B	Cream	Concrete	0.00	Negative	
135	Area 1-1	Wall C	Cream	Concrete	0.03	Negative	
136	Area 1-1	Wall D	Cream	Concrete	0.02	Negative	
137	Area 1-1	Window Shutter	White	Metal	0.01	Negative	
138	Area 1-1	Window Shutter	White	Metal	0.01	Negative	
139	Area 1-1	Window Shutter	White	Metal	0.01	Negative	
140	Area 1-1	Door	Brown	Metal	0.00	Negative	
141	Area 1-1	Door Frame	Brown	Metal	0.00	Negative	
142	Area 1-1	Door	Brown	Metal	0.00	Negative	
143	Area 1-1	Door Frame	Brown	Metal	0.00	Negative	
144	Area 1-1	Door	Brown	Metal	0.00	Negative	
145	Area 1-1	Door Frame	Brown	Metal	0.01	Negative	
146	Area 1-1	Door	Brown	Metal	0.02	Negative	
147	Area 1-1	Door Frame	Brown	Metal	0.03	Negative	
148	Area 1-2	Floor Tile	Cream	Ceramic	0.00	Negative	
149	Area 1-2	Wall Tile	White	Ceramic	0.00	Negative	
150	Area 1-2	Window Shutter	White	Metal	0.00	Negative	
151	Area 1-2	Window Shutter	White	Metal	0.00	Negative	
152	Area 1-2	Urinal	White	Ceramic	0.00	Negative	
153	Area 1-2	Urinal	White	Ceramic	0.00	Negative	
154	Area 1-2	Lavatory	White	Ceramic	0.00	Negative	
155	Area 1-2	Lavatory	White	Ceramic	0.00	Negative	
156	Area 1-2	Lavatory	White	Ceramic	0.00	Negative	
157	Area 1-2	Toilet	White	Ceramic	0.00	Negative	
158	Area 1-2	Toilet	White	Ceramic	0.03	Negative	
159	Area 1-2	Toilet	White	Ceramic	0.00	Negative	
160	Area 1-2	Toilet	White	Ceramic	0.00	Negative	
161	Area 1-2	Wall A	Light Green	Concrete	0.00	Negative	
162	Area 1-2	Wall B	Light Green	Concrete	0.00	Negative	
163	Area 1-2	Wall C	Light Green	Concrete	0.00	Negative	
164	Area 1-2	Wall D	Light Green	Concrete	0.00	Negative	
165	Area 1-2	Ceiling	Varnish	Wood	0.02	Negative	
166	Area 1-2	Door	Light Green	Metal	0.00	Negative	
167	Area 1-2	Door Frame	Light Green	Metal	0.00	Negative	
168	Area 1-3	Door	Brown	Metal	0.00	Negative	
169	Area 1-3	Door Frame	Brown	Metal	0.00	Negative	
170	Area 1-3	Lavatory	White	Ceramic	0.00	Negative	
171	Area 1-3	Lavatory	White	Ceramic	0.00	Negative	
172	Area 1-3	Lavatory	White	Ceramic	0.00	Negative	
173	Area 1-3	Wall A	Cream	Concrete	0.00	Negative	
174	Area 1-3	Wall B	Cream	Concrete	0.00	Negative	
175	Area 1-3	Wall C	Cream	Concrete	0.00	Negative	
176	Area 1-3	Wall D	Cream	Concrete	0.00	Negative	
177	Area 1-3	Wall Tile	White	Ceramic	0.00	Negative	
178	Area 1-3	Floor Tile	Cream	Ceramic	0.00	Negative	
179	Area 1-3	Toilet	White	Ceramic	0.60	Negative	
180	Area 1-3	Toilet	White	Ceramic	0.70	Negative	
181	Area 1-3	Toilet	White	Ceramic	0.76	Negative	
182	Exterior Side B	Wall B	Pink	Concrete	0.00	Negative	
183	Exterior Side B	Soffit	Pink	Wood	0.00	Negative	
184	Exterior Side B	Fascia	Pink	Wood	0.00	Negative	
185	Exterior Side A	Wall A	Pink	Concrete	0.00	Negative	
186	Exterior Side A	Soffit	Pink	Wood	0.00	Negative	
187	Exterior Side A	Fascia	Pink	Wood	0.00	Negative	
188	Exterior Side A	Column	Pink	Concrete	0.00	Negative	

PROJECT:	Various Buildings Located at Fort Allen, Juana Díaz PR			CLIENT: PRNG			
DATE:	6/27/2025	Building 233		LBP Inspector: Alicia García			
Sample ID.	Functional Space	Location	Color	Subst.	XRF Reading mg/cm2	Pos/Neg	Comments
189	Exterior Side C	Wall C	Pink	Concrete	0.00	Negative	
190	Exterior Side C	Soffit	Pink	Wood	0.00	Negative	
191	Exterior Side C	Fascia	Pink	Wood	0.00	Negative	
192	Exterior Side C	Column	Pink	Concrete	0.03	Negative	
193	Exterior Side C	Column	Pink	Concrete	0.00	Negative	
194	Exterior Side D	Wall D	Pink	Concrete	0.00	Negative	
195	Exterior Side D	Soffit	Pink	Wood	0.00	Negative	
196	Exterior Side D	Fascia	Pink	Wood	0.00	Negative	